

Under Review Notification

Raised By: Michelle Gagnon-Donovan

Product #: D139-1019

Date: 19.01.11

Product Name: Skylight

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D139-1019-011/012	IIN-D139-1019 Rev E	Y	Y	N	Y	N	Y	Y	19-505	
D5621-041/-042/-043/-044	D5621 Rev C	Y	Y	N	Y	N	Y	Y	19-505	Waiting for Burn Test Results

Description of Issue:

D5621 placed under review until material is approved. Burn Test of Tuffak GP is required prior to shipment.

Distribution:

- | | | | |
|----------------------------|------------------------------|--------------------------|--------------------------------------|
| VP Operations | Director of Engineering | Customer Support Manager | Technical Support |
| Director of Operations | Chief Engineer | Production Engineers | Product Manager - Solutions Provider |
| Director Quality Assurance | Engineering Project Managers | Production Planners | Supply Chain Director / Senior Buyer |
| QC Coordinator | Engineering Clerk | Purchasing Manager | Marketing Eugene |